



(RC: 485454)

Seasystems Marine Integrated Services Limited

SOLAS

Int'l Convention for the Safety of Life at Sea, 1974

CERTIFICATE OF RE-INSPECTION


Year 2019	Month 10	Day 30	Name of Ship TMC ZION	Classification Society BV	Certificate No: 01601997
IMO NO: 9822968	Flag State NIGERIA	Call Sign: 5NYL7	Port of Registry LAGOS	Place of service ONNE	Owner: TAMROSE VENTURES

SELF CONTAINED BREATHING APPARATUS (SCBA)

Description of type				Description of working codes				
SCBA = self-contained Breathing apparatus				1. = Inspected	5 = Replaced mask			
BAS = Breathing Apparatus Set				2. = Contents checked	7. = External Maintenance			
				3. = Hydro tested	8. = New SCBA			
				4. = Refilled	9. = Label attached			
S/N	TYPE	CYL. NO	MAKE	CAPACITY	TEST PRESSURE	LHT	LOCATION	WORKING CODES
1	SCBA	OKZ 129 UT	SCOTT	300 BAR	450 BAR	06/2016	MAIN DECK	1+2+9
BREATHING APPARATUS SETS (BAS)								
1	BAS	A140724	SCOTT	-	-	MAIN DECK		1+9

This is to certify that the above mentioned safety equipment, were duly inspected and necessary maintenance made. They are in good condition for operation in any emergency

THIS CERTIFICATE IS VALID FOR ONE YEAR FROM THE ABOVE DATE
NEXT INSPECTION DATE: OCTOBER, 2020



TAKAM CELESTIN

Head Office: Harbour Road, Medical Centre Complex, ONNE, P.O. Box 221 Nchia Eleme Nig.;

Tel: 234-84-302888, 08162092052

E-mail: seasystemsmarine@yahoo.com sales@seasystemsmarine.com www.seasystemsmarine.com



(RC: 485454)

Seasystems Marine Integrated Services Limited

SOLAS

Int'l Convention for the Safety of Life at Sea, 1974

CERTIFICATE OF RE-INSPECTION


Year 2019	Month 10	Day 30	Name of Ship TMC ZION	Classification Society BV	Certificate No: 01601998
IMO NO: 9822968	Flag State NIGERIA	Call Sign: 5NYL7	Port of Registry LAGOS	Place of service ONNE	Owner: TAMROSE VENTURES

EMERGENCY ESCAPE BREATHING DEVICE (EEBD)

Description of type					Description of working codes			
EEBD = Emergency Escape Breathing Device					1. = Inspected	5. = Replaced mask		
					2. = Contents checked	6. = External Maintenance		
					3. = Hydro tested	7. = New EEBD		
					4. = Refilled	8. = Label attached		
S/N	TYPE	CYL. NO	MAKE	CAPACITY	TEST PRESSURE	LIFE DATE	LOCATION	WORKING CODES
1	EEBD	M734582	OCENCO	200 BAR	300 BAR	02/2032	ENGINE ROOM	1+2+8

This is to certify that the above mentioned safety equipment, were duly inspected and necessary maintenance made. They are in good condition for operation in any emergency

THIS CERTIFICATE IS VALID FOR ONE YEAR FROM THE ABOVE DATE
NEXT INSPECTION DATE: OCTOBER, 2020



TAKAM CELESTIN

Head Office: Harbour Road, Medical Centre Complex, ONNE, P.O. Box 221 Nchia Eleme Nig.;

Tel: 234-84-302888, 08162092052

E-mail: seasystemsmarine@yahoo.com sales@seasystemsmarine.com www.seasystemsmarine.com



(RC: 485454)

Seasystems Marine Integrated Services Limited

SOLAS

Int'l Convention for the Safety of Life at Sea, 1974

CERTIFICATE OF RE-INSPECTION

Year 2019	Month 10	Day 30	Name of Ship TMC ZION	Classification Society BV	Certificate No: 01602001
IMO NO: 9822968	Flag State NIGERIA	Call Sign: 5NYL7	Port of Registry LAGOS	Place of service ONNE	Owner: TAMROSE VENTURES

NOVEC 1230 FIXED SYSTEM


Description of type	Description of working codes
1. = Inspection 2. = Contents checked by weighing 3. = Recharged 4. = Hydro test 5. = Valve renewal	7. = Valve repair 8. = External maintenance 9. = New cylinder 10. = Blowing of lines 11. = Label attached

LOCATION: ENGINE ROOM

S/N	MAKE	CYL. NO	CAPACITY KG/L	LAST HYD. TEST	WORKING CODES
1	KIDDE	144062098	99	10/2018	1+2+11

This is to certify that the above mentioned safety equipment, were duly inspected and necessary maintenance made. They are in good condition for operation in any emergency

THIS CERTIFICATE IS VALID FOR ONE YEAR FROM THE ABOVE DATE
NEXT INSPECTION DATE: OCTOBER, 2020




TAKAM CELESTIN

Head Office: Harbour Road, Medical Centre Complex, ONNE, P.O. Box 221 Nchia Eleme Nig,;

Tel: 234-84-302888, 08162092052

E-mail: seasystemsmarine@yahoo.com sales@seasystemsmarine.com www.seasystemsmarine.com



(RC: 485454)

Seasystems Marine Integrated Services Limited

SOLAS

Int'l Convention for the Safety of Life at Sea, 1974

CERTIFICATE OF RE-INSPECTION


Year 2019	Month 10	Day 30	Name of Ship TMC ZION	Classification Society BV	Certificate No: 01601999
IMO NO: 9822968	Flag State NIGERIA	Call Sign: 5NYL7	Port of Registry LAGOS	Place of service ONNE	Owner: TAMROSE VENTURES
Description of type			Description of working codes		
DCP = Dry Chemical Powder W = Water CO ₂ = Carbon Dioxide BCF = Halon 121			F = Foam WM = Water Mist WC = Wet Chemical IIM = Immersion Suit		
			1 = Inspection 2 = Contents checked 3 = Hydrostatic test 4 = Refilled		
			5 = Valve replaced 6 = External Maintenance 7 = New extinguisher 8 = Label attached		

PORTABLE FIRE EXTINGUISHERS

S/N	TYPE	CAPACITY	MAKE	CYL S/N	LHT	LOCATION	WORKING CODES
1	DCP	6KG	HYGRAPHHA	126524	05/2017	MESS ROOM	1+2+8
2	DCP	6KG	HYGRAPHHA	126106	05/2017	TECH SPACE	1+2+8
3	DCP	6KG	HYGRAPHHA	125905	05/2017	BOW THRUSTER	1+2+8
4	DCP	6KG	HYGRAPHHA	A037001	05/2017	ENGINE ROOM	1+2+8
5	DCP	6KG	HYGRAPHHA	068569	01/2017	TECH SPACE	1+2+8
6	DCP	6KG	HYGRAPHHA	122218	03/2017	TECH SPACE	1+2+8
7	CO2	5KG	HYGRAPHHA	C003772	01/2017	BRIDGE DECK	1+2+8
8	CO2	5KG	HYGRAPHHA	013354	01/2017	MESS ROOM	1+2+8
9	CO2	5KG	HYGRAPHHA	C005003	01/2017	TECH SPACE	1+2+8
10	CO2	5KG	HYGRAPHHA	C005039	01/2017	TECH SPACE	1+2+8
11	CO2	5KG	HYGRAPHHA	0004261	01/2017	TECH SPACE	1+2+8
12	CO2	5KG	HYGRAPHHA	C005244	01/2017	TECH SPACE	1+2+8
13	CO2	5KG	HYGRAPHHA	C003963	01/2017	TECH SPACE	1+2+8
14	CO2	5KG	HYGRAPHHA	C004453	01/2017	ENGINE ROOM	1+2+8
15	CO2	5KG	HYGRAPHHA	C005550	01/2017	ENGINE ROOM	1+2+8
16	CO2	5KG	HYGRAPHHA	C004160	01/2017	ENGINE ROOM	1+2+8
17	CO2	5KG	HYGRAPHHA	C004518	01/2017	ENGINE ROOM	1+2+8
18	CO2	5KG	HYGRAPHHA	C003631	01/2017	ENGINE ROOM	1+2+8
19	CO2	5KG	HYGRAPHHA	C004063	01/2017	ENGINE ROOM	1+2+8
20	CO2	5KG	HYGRAPHHA	C003051	01/2017	ENGINE ROOM	1+2+8
21	CO2	5KG	HYGRAPHHA	C004409	01/2017	ENGINE ROOM	1+2+8
22	FOAM	9L	HYGRAPHHA	A012857	05/2017	MESS ROOM	1+2+8
23	FOAM	9L	HYGRAPHHA	A061413	05/2017	TECH SPACE	1+2+8
24	FOAM	9L	HYGRAPHHA	101294	05/2017	ENGINE ROOM	1+2+8
25	FOAM	9L	HYGRAPHHA	A060995	05/2017	TECH SPACE	1+2+8
26	FOAM	9L	HYGRAPHHA	A053948	05/2017	TECH SPACE	1+2+8
27	FOAM	9L	HYGRAPHHA	A061356	05/2017	TECH SPACE	1+2+8
28	FOAM	9L	HYGRAPHHA	101433	01/2017	TECH SPACE	1+2+8

This is to certify that the above mentioned safety equipment, were duly inspected and necessary maintenance made. They are in good condition for operation in any emergency

THIS CERTIFICATE IS VALID FOR ONE YEAR FROM THE ABOVE DATE
NEXT INSPECTION DATE: **OCTOBER, 2020**



TAKAM CELESTIN
TAKAM CELESTIN

Head Office: Harbour Road, Medical Centre Complex, ONNE, P.O. Box 221 Nchia Eleme Nig.;

Tel: 234-84-302888, 08162092052

E-mail: seasystemsmarine@yahoo.com sales@seasystemsmarine.com www.seasystemsmarine.com



(RC: 485454)

Seasystems Marine Integrated Services Limited

SOLAS

Int'l Convention for the Safety of Life at Sea, 1974

CERTIFICATE OF RE-INSPECTION


Year 2019	Month 10	Day 30	Name of Ship TMC ZION	Classification Society BV	Certificate No: 01602000
IMO NO: 9822968	Flag State NIGERIA	Call Sign: 5NYL7	Port of Registry LAGOS	Place of service ONNE	Owner: TAMROSE VENTURES
Description of type			Description of working codes		
DCP = Dry Chemical Powder			1 = Inspection		
W = Water			2 = Contents checked		
CO ₂ = Carbon Dioxide			3 = Hydrostatic test		
BCF = Halon 121			4 = Refilled		
F = Foam			5 = Valve replaced		
WM = Water Mist			6 = External Maintenance		
WC = Wet Chemical			7 = New extinguisher		
IIM = Immersion Suit			8 = Label attached		

PORTABLE FIRE EXTINGUISHERS

S/N	TYPE	CAPACITY	MAKE	CYL S/N	LHT	LOCATION	WORKING CODES
29	FOAM	9L	HYGRAPHHA	A061284	01/2017	ENGINE ROOM	1+2+8
30	FOAM	9L	HYGRAPHHA	A121753	01/2017	ENGINE ROOM	1+2+8
31	FOAM	9L	HYGRAPHHA	A061117	01/2017	ENGINE ROOM	1+2+8
32	FOAM	9L	HYGRAPHHA	A061716	01/2017	ENGINE ROOM	1+2+8
33	FOAM	9L	HYGRAPHHA	A101272	01/2017	ENGINE ROOM	1+2+8
34	FOAM	9L	HYGRAPHHA	A101354	01/2017	ENGINE ROOM	1+2+8
35	FOAM	9L	HYGRAPHHA	A061342	01/2017	ENGINE ROOM	1+2+8
36	FOAM	9L	HYGRAPHHA	A061104	01/2017	ENGINE ROOM	1+2+8

This is to certify that the above mentioned safety equipment, were duly inspected and necessary maintenance made. They are in good condition for operation in any emergency

THIS CERTIFICATE IS VALID FOR ONE YEAR FROM THE ABOVE DATE
NEXT INSPECTION DATE: OCTOBER, 2020



TAKAM CELESTIN

TAKAM CELESTIN

Head Office: Harbour Road, Medical Centre Complex, ONNE, P.O. Box 221 Nchia Eleme Nig.;

Tel: 234-84-302888, 08162092052

E-mail: seasystemsmarine@yahoo.com sales@seasystemsmarine.com www.seasystemsmarine.com